



FIG.1





ASSIGNING PROCESS OF EXPOSURE GRADATIONS TO RESPECTIVE ELEMENTS

	0	1	2	3	4	5	6	7	241	765
R ELEMENT 1	0	1	1	1	2	2	2	3	81	255
R ELEMENT 2	0	0	1	1	1	2	2	2	80	255
R ELEMENT 3	0	0	0	1	1	1	2	2	80	255

FIG.4

ASSIGNING PROCESS OF EXPOSURE GRADATIONS TO RESPECTIVE ELEMENTS

	0	1	2	3	4	5	6	7	255	256	257	510	511	765
R ELEMENT 1	0	1	2	3	4	5	6	7	255	255	255	255	255	255
R ELEMENT 2	0	0	0	0	0	0	0	0	0	1	2	255	255	255
R ELEMENT 3	0	0	0	0	0	0	0	0	0	0	0	0	1	255




FIG.6

	n_i	m_i	$n_i \times (m_i - 1) + 1$
R	4	256	1021
G	3	341	1021
B	2	511	1021

FIG.7

	n_i	m_i	$n_i \times (m_i - 1) + 1$
R	4	256	1021
G	3	512	1534
B	2	512	1023

FIG.8
PRIOR ART




FIG. 9




FIG.10




FIG. 11




FIG.12

	n_i	m_i	$n_i \times (m_i - 1) + 1$
R	32	128	4065
G	16	256	4081
B	16	256	4081

FIG.13




FIG.14

